



# TURBO TECHNOLOGY

CATEGORY	UPDATES	IMAGE REFERENCE	LEVO GEN 2 COMPATIBILITY NOTE
MOTOR	<ul style="list-style-type: none"> <li>Specialized 2.2</li> </ul> <p>Note on naming: The 2.1 was renamed as the 2.2 motor to align with the launch of the all-new Turbo Levo and to reflect the hardware &amp; firmware improvements we've made to motor reliability/rideability over the past two years.</p>		<p>Motor unit as such is identical for both generations, specific.</p> <p>Levo Gen3 hardware:</p> <ul style="list-style-type: none"> <li>Steel TX 25/30 motor bolts (more durable)</li> <li>3 sizes of the motor mount bracket, specific allows optimally orientating the motor in each are easier to access; more service friendly</li> <li>S1/S2 (engraved on bracket)</li> <li>S3/S4 (engraved on bracket)</li> <li>S5/S6 (engraved on bracket)</li> <li>Thru axle at forward motor mounts</li> <li>New motor inserts/spacers: pressed in by plastic to better distribute loads and dampen vibrations</li> </ul>

CATEGORY	UPDATES	IMAGE REFERENCE	LEVO GEN 2 COMPATIBILITY NOTE
BATTERY HARDWARE	<ul style="list-style-type: none"> <li>Identical core packs (700 wh and 500 Wh)</li> <li>New battery hardware (expander, rock guard + door)</li> <li>New fixation screw with knurled brim (helps to thread in screw by hand before tightening)</li> <li>Motor covers feature extended coverage at edges to have less contamination in motor area</li> </ul>		<p>All hardware not interchangeable between Levo Gen3 and Levo Gen2 (e.g. chainstay protector, frame protectors, derailleur hanger). Those parts are specific.</p>